Fall GAA Meeting 2021

FAIRBANKS AIR TRAFFIC CONTROL

Pilot Outreach Representatives: Corey Shaw "CW" Alexia Snyder "LS" FAI Tower Manager:

Tim Long

Email: faipilotoutreach@gmail.com Phone: 907-474-0452 (Recorded) 907-474-0050 (Office)

October 12, 2021





Discussion Points

- Introduction
- Staffing and Training
- Construction Season Wrap-up
- New TWY B Procedures
- Deviations
- Emergencies
- Questions



Staffing & Training

Current

15

Certified Controllers

Trainees



6

Construction Wrap-Up

- 2 reported issues w/ construction vehicles cutting off A/C. (Airport Ops was quick in handling the issues)
 - 3 reported incidents w/ A/C attempting to depart opposite direction 2L/20R @ B.
 - All were unfamiliar pilots
 - 2 were immediately caught by ATC and corrected before the A/C started take-off roll.
 - 1 resulted in A/C on final being sent around.
 - (Immediately after runway change.)

Taxiway Bravo Procedures

- Ground Control will have control of TWY Bravo, starting at the movement area WEST of the Gate.
 ATC will have no control/responsibility over the gate.
- Utilize the new pull out when taxiing to RWY 2L/20R
 @Bravo. Traffic exiting 2L/20R will usually be given priority.
- When doing a run-up, use the elephant ear. When ready for departure, stay in elephant ear, and call tower.

May-Sept. Deviations

• Vehicle/Pedestrian 2 Vehicle 3 Pedestrian 2 Bicycle 1 Jogger Wrong Surface Uncontrolled Taxiway C Wrong Direction 3 2L/20R @ B Take-off without Clearance • 1 of Floatpond 20

Emergencies

ATC required info
Callsign
Nature of the Emergency
Pilot's Intentions
Other pertinent info

(Dependent to Nature of Emergency)
Number of Persons on Board

Fuel in Pounds

Qualifications (Student Pilot, IFR capable/equipped, etc.)

Questions?

Email: faipilotoutreach@gmail.com Phone: 907-474-0452 (Recorded) 907-474-0050 (Office)